

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:					
Company	Mike W. Glasson Environmental Coordinator				
OGM	Pete Hess Environmental Scientist III				

Inspection Report

Permit Number:	C0070041			
Inspection Type:	PARTIAL			
Inspection Date:	Wednesday, September 27, 2006			
Start Date/Time:	9/27/2006 8:57:00 AM			
End Date/Time:	9/27/2006 10:00:00 AM			
Last Inspection:	Wednesday, August 23, 2006			

Inspector: Pete Hess, Environmental Scientist III

Weather: Clear, cool.

InspectionID Report Number: 1103

Types of Operations

Accepted by: whedberg

Thursday, October 05, 2006

Date

0/17/2006

Permitee: WEST RIDGE RESOURCES
Operator: WEST RIDGE RESOURCES

Site: WEST RIDGE MINE

Address: PO BOX 1077, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

6,114.89	Total Permitted		
29.06	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

✓ Federal	✓ Underground
✓ State	Surface
☐ County	☐ Loadout
Fee	Processing
Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee is current relative to the quarterly submittal of surface and ground water monitoring information for the West Ridge Mine permit area. Thus, the Permittee continues to meet the Special Permit Condition included as Attachment "A" of the current State permit.

Inspector's Signature:

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070041 Inspection Type: PARTIAL

Inspection Date: Wednesday, September 27, 2006

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V			
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	V		✓	
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		V		
13.	Revegetation		✓		
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing	V			
16.b	Roads: Drainage Controls	V			
17.	Other Transportation Facilities	V			
18.	Support Facilities, Utility Installations	V			
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070041 Inspection Type: PARTIAL

Inspection Date: Wednesday, September 27, 2006

Page 3 of 3

4.c Hydrologic Balance: Other Sediment Control Measures

Several of the straw bale sediment control dikes which are in place in the ditches designated as DD-4 and UD-15 were noted as being at capacity relative to sediment level or near capacity (See Map 7-2, Mine Site Drainage Map). The structures would still function through a small event. Mr. Glasson agreed to address the needed maintenance.

10. Slides and Other Damage

A minor erosion gully was observed on the slope beneath the crusher building / belt reclaim to the truck loading facility. The erosion is caused by wash down water from the upper levels of the crusher building and the concrete pad reporting to the area at the edge of the crusher building pad. The Division suggested that a piece of conveyor belting be placed here to reduce the erosive potential of the water reporting down this slope. A half-round culvert was suggested by the Permittee to armour the area. The Permittee was informed that an update of Map 7-2, Mine Site Drainage Map, would be necessary to show this modification to the currently approved surface drainage plan.